

PODATKOVNA TABELA: elektrika

Poz.	Ko.	Opis	El. moč (kW/ko)	Skupna el. moč (kW)	Varovanje (A)	Napetost (V)
2.	1	Pralni stroj FX105	9.8	9.8	20	3x400
3.	1	Pralni stroj FX180	13.5	13.5	25	3x400
4.	1	Pralni stroj FX240	20	20	32	3x400
5.	1	Sušilni stroj T13HP	4.3	4.3	16	3x400
6.	2	Sušilni stroj T16HP	4.3	8.6	16	3x400
7.	1	Likalni stroj I25–140	7.2	7.2	16	3x400
8.	1	Likalna miza FVC	5.5	5.5	16	3x400

PRIKLJUČNA NAPETOST: 3AC+N 400V, 50Hz
SKUPNA PRIKLJUČNA MOČ: 68,9 kW
FUNKCIONALNI KOEFICIENT: 0.6÷0.8

OPOMBA:
Za vsakim strojem se montira grebenasto stikalo z prostim dostopom za operaterja. Od stikala se pusti prosti konec kabla z zaščito kabla – dolžine najmanj 3m.

REMARKS:
WATER CONNECTION:
Inlet valves FX washing machines 3/4" for cold and hot water are delivered with the machine.
Mount shut-off valves to the water supply pipes, it makes easy the maintenance and cleaning of filter delivered with machines.
The shut-off valves are not a part of delivery.
For connection of particular machines to water inlet shut-off valves we recommend to use delivered flexible hoses with couplings.

PODATKOVNA TABELA: porabe

Poz.	Ko.	Opis	*Poraba vode		Pritisk vode (bar)
			hl. voda mehka+trda (l/cikel/ko)	topla voda (l/cikel/ko)	
4.	1	Pralni stroj FX240	120	74	3÷5
3.	1	Pralni stroj FX180	123	54	3÷5
2.	1	Pralni stroj FX105	72	33	3÷5
SKUPAJ			315	161	

*Poraba vode–Program št.2–Pisano perilo 60°C brez koraka predpranja

PODATKOVNA TABELA: odpadne vode

Poz.	Ko.		Količina odpadne vode (l/min./kom)
4.	1	Pralni stroj FX240	210
3.	1	Pralni stroj FX180	210
2.	1	Pralni stroj FX105	210
SKUPAJ			630

OPOMBE_ODTOK:
Drenažni sistem vključno s sifonom in lovilcem, skladen z EN 12056. Maximal waste water temperature of program No.1 "Hot wash 90°C" is 85÷88°C. Minimal thermal endurance of the discharge pipe must be 90°C.

REMARKS:
WATER CONNECTION:
Inlet valves FX washing machines 3/4" for cold and hot water are delivered with the machine.
Mount shut-off valves to the water supply pipes, it makes easy the maintenance and cleaning of filter delivered with machines.
The shut-off valves are not a part of delivery.
For connection of particular machines to water inlet shut-off valves we recommend to use delivered flexible hoses with couplings.

CWH 20l/min / 3÷5bar 1580mm 3/4"ET
DO 210l/min / gravity 383mm ϕ76mm
EL 3.6kW / 25A 1233mm 5x2.5mm² Cu

- vrsta kabla, dimenzija priključka
- višina priključka od tal
- moč, pretok/ varovanje, priporočen pritisk
- legenda

LEGENDA:
CWS HLADNA MEHKA VODA
CWH HLADNA TRDA VODA
HW TOPLA MEHKA VODA
DO IZPUST VODE
EL PRIKLJUČEK ELEKTRIKE
EO ODVOD ZRAKA
ET ZUNANJI NAVOJ

LEGENDA PRALNICE PERILA: natančen opis glej popis!

Poz	Kom	Oprema
2.	1	Industrijski pralni stroj kot npr. Primus FX105
3.	1	Industrijski pralni stroj kot npr. Primus FX180
4.	1	Industrijski pralni stroj kot npr. Primus FX240
5.	1	Industrijski sušilni stroj kot npr. Primus T13HP
6.	2	Industrijski sušilni stroj kot npr. Primus T16HP
7.	1	Likalni stroj kot npr. Primus I25–140
8.	1	Likalna miza kot npr. Pony FVC

POGLED Z DESNE FX240



POGLED Z DESNE FX180



POGLED Z DESNE FX105